

**GENIE ASSURE**

INSPECT · VERIFY · DELIVER

Vehicle Inspection Report

Comprehensive multi-point inspection covering 196+ quality checks

OVERALL SCORE

3.2/5

CHECKS COMPLETED

195/196

VEHICLE

Tata Tiago 2021

2020 | Manual | Petrol

Registration No. **KA36P4148**Odometer **36,000 km**Ownership **1**

PREPARED FOR

Test User

9900609455

Location **Bengaluru**Inspection Date **18 Sep, 2026**Inspected By **Suresh Babu**

Scan to verify this report

REPORT ID · GBR-S5PF2EAL

REPORT GENERATED ON 14 SEP, 2026 · POWERED BY GENIEBIKEZ





OVERALL SUMMARY

A comprehensive evaluation of the vehicle across 6 key categories.

Verdict: Not recommended without major repairs



OVERALL RATING

Vehicle Details

Vehicle	Tata Tiago 2021 (2020 Manual Petrol)
Customer	Test User · 9900609455
Registration Number	KA36P4148
Odometer Reading	36,000 kms
Engine Number	sdfsfsfs31
Chassis Number	313131
Ownership Number	1
Fuel / Transmission	Petrol · Manual
Inspection Location	Bengaluru
Inspected By	Suresh Babu (G-Captain)

VEHICLE CONDITION

Good

CHECKS COMPLETED

195/196

GOOD

67

NEEDS ATTENTION

128

REPORT INFORMATION

Report ID	GBR-S5PF2EAL	Inspection ID	GBI-CUQHJ64B
Inspection Date	18 Sep, 2026	Inspected By	Suresh Babu
Submitted On	14 Sep, 2026	Approved On	14 Sep, 2026
Approved By	Admin	Report Status	Approved

RATING SCALE

● Good — no issues found	● Fair — monitor / minor	● Poor — needs attention	● Not checked
--------------------------	--------------------------	--------------------------	---------------

Each parameter is rated and converted to a 0-5 score. Section and overall scores are the weighted average of all checked parameters.

TYRE HEALTH

Tyre	Tread Depth	Life Remaining
Front Left	1.0 mm	13% life remaining
Front Right	2.0 mm	25% life remaining
Rear Left	3.0 mm	38% life remaining
Rear Right	4.0 mm	50% life remaining
Spare	1.0 mm	13% life remaining

GENIE ASSURE



HEALTH REPORT SUMMARY

CRITICAL — NEEDS ATTENTION (52)

Exterior & Tyres · Front Left Door

Exterior & Tyres · Rear Right Door

Exterior & Tyres · Rear Left Quarter Panel

Exterior & Tyres · Tail Lamp Left

Exterior & Tyres · Front Windshield

Exterior & Tyres · Window Glass Rear Left

Exterior & Tyres · Overspray / Repaint Evidence

Exterior & Tyres · Chrome & Body Trims

Exterior & Tyres · Tyre Rear Right

Engine & Transmission · Engine Idling Smoothness

Engine & Transmission · Engine Noise / Knocking

Engine & Transmission · Engine Vibration

Engine & Transmission · Engine Oil Level

Engine & Transmission · Radiator Condition

Engine & Transmission · Radiator Fan Operation

Engine & Transmission · Thermostat

Engine & Transmission · Engine Bay Cleanliness

Engine & Transmission · Battery Condition

Engine & Transmission · Neutral Gear

Engine & Transmission · Differential Noise

Engine & Transmission · Catalytic Converter

Electricals & Interiors · Speedometer

Electricals & Interiors · Fuel Gauge

Electricals & Interiors · Headlights High Beam

Electricals & Interiors · Right Turn Indicators

Electricals & Interiors · Fog Light Operation

Electricals & Interiors · Power Window Rear Right

Electricals & Interiors · Infotainment / Head Unit

Electricals & Interiors · Parking Sensors

Electricals & Interiors · Front Seat Upholstery

Electricals & Interiors · Front Right Door Pad

Electricals & Interiors · Gear Knob / Lever

Electricals & Interiors · Interior Odour

Electricals & Interiors · Driver Seat Belt

Steering, Suspension & Brakes · Steering Return to Centre

Steering, Suspension & Brakes · Steering Column / Joints

Steering, Suspension & Brakes · Suspension Rear Left

Steering, Suspension & Brakes · Rear Shock Absorbers

Steering, Suspension & Brakes · Tie Rod Ends

Steering, Suspension & Brakes · Wheel Bearing Front Right

Steering, Suspension & Brakes · Brake Pedal Feel

Steering, Suspension & Brakes · Front Brake Discs

Steering, Suspension & Brakes · Drum Brakes (If Applicable)

Steering, Suspension & Brakes · Brake Lines / Hoses

Air Conditioning · AC Cooling Performance

Air Conditioning · AC Condenser

Air Conditioning · AC Noise / Rattling

Other Details · Number of Keys Provided

Other Details · Spare Key

Other Details · First Owner Vehicle

Other Details · Total Number of Owners

Other Details · Fuel Type

MINOR — MONITOR (76)

Exterior & Tyres · Boot Lid

Exterior & Tyres · Front Right Door

Exterior & Tyres · Front Bumper

Exterior & Tyres · Front Right Fender

Exterior & Tyres · Rear Right Quarter Panel

Exterior & Tyres · Headlamp Right

Exterior & Tyres · Tail Lamp Right

Exterior & Tyres · Front Fog Lamp Left

Exterior & Tyres · Front Fog Lamp Right

Exterior & Tyres · ORVM Left

Exterior & Tyres · Rear Windshield

Exterior & Tyres · Window Glass Front Right

Exterior & Tyres · Window Glass Rear Right

Exterior & Tyres · Overall Paint Condition

Exterior & Tyres · Panel Gap Alignment

Exterior & Tyres · Tyre Front Left

Exterior & Tyres · Tyre Rear Left

Exterior & Tyres · Spare Tyre Condition

Exterior & Tyres · Rear Number Plate

Engine & Transmission · Engine Start (Cold & Hot)

Engine & Transmission · Engine Oil Condition / Colour

Engine & Transmission · Coolant Condition

Engine & Transmission · Water Pump

Engine & Transmission · Drive / Serpentine Belt

Engine & Transmission · Fuel Lines / Leaks

Engine & Transmission · Oil Leaks (Engine Bay)

Engine & Transmission · Battery Terminals / Corrosion

Engine & Transmission · Spark Plugs

Engine & Transmission · Gear Shift Smoothness

Engine & Transmission · Reverse Gear

Engine & Transmission · Drive Shaft / CV Joints

Engine & Transmission · Engine Mounts

Engine & Transmission · Exhaust Smoke (White / Black / Blue)

Engine & Transmission · Check Engine Light

Electricals & Interiors · Dashboard Warning Lights

Electricals & Interiors · Odometer

Electricals & Interiors · Horn

Electricals & Interiors · Left Turn Indicators

Electricals & Interiors · Hazard Lights

Electricals & Interiors · Reverse Light

Electricals & Interiors · Interior Cabin Lights

Electricals & Interiors · Power Window Rear Left

Electricals & Interiors · Central Locking

Electricals & Interiors · Steering Mounted Controls

Electricals & Interiors · Speakers

Electricals & Interiors · Reverse Camera

Electricals & Interiors · Passenger Seat Adjustment

Electricals & Interiors · Front Left Door Pad

Electricals & Interiors · Rear Right Door Pad

Electricals & Interiors · Handbrake Lever

Electricals & Interiors · Roof Lining

Electricals & Interiors · Cabin Cleanliness

Steering, Suspension & Brakes · Steering Free Play

Steering, Suspension & Brakes · Power Steering Leaks

Steering, Suspension & Brakes · Suspension Front Right

Steering, Suspension & Brakes · Front Shock Absorbers

Steering, Suspension & Brakes · Ball Joints

Steering, Suspension & Brakes · Wheel Bearing Front Left

Steering, Suspension & Brakes · Wheel Bearing Rear Right

Steering, Suspension & Brakes · Brake Fluid Level

Steering, Suspension & Brakes · Rear Brake Discs

Steering, Suspension & Brakes · Rear Brake Pads

Steering, Suspension & Brakes · Handbrake / Parking Brake Effectiveness

Air Conditioning · AC Compressor Operation

Air Conditioning · AC Vents / Airflow
Air Conditioning · AC Evaporator
Air Conditioning · Cabin Air Filter
Air Conditioning · Heater Operation
Air Conditioning · Climate Control Panel
Other Details · RC Book Availability
Other Details · Service History Available
Other Details · Tool Kit
Other Details · Ownership Documents
Other Details · Accident History Reported
Other Details · Year of Manufacture
Other Details · Vehicle Usage Type (Personal / Commercial)

Not recommended without major repairs

SECTION-WISE SCORES

Each section is evaluated across multiple parameters to give an accurate overall picture.

Exterior & Tyres 18 Good · 19 Fair · 9 Needs Attention (46/47 checked)	3.4/5
Engine & Transmission 8 Good · 15 Fair · 12 Needs Attention (35/35 checked)	2.8/5
Electricals & Interiors 18 Good · 18 Fair · 13 Needs Attention (49/49 checked)	3.2/5
Steering, Suspension & Brakes 12 Good · 11 Fair · 10 Needs Attention (33/33 checked)	3.1/5
Air Conditioning 3 Good · 6 Fair · 3 Needs Attention (12/12 checked)	3.0/5
Other Details 8 Good · 7 Fair · 5 Needs Attention (20/20 checked)	3.3/5



VEHICLE IMAGES

Photographic evidence captured during the inspection.



Front View



Rear View



Left Side



Right Side



Dashboard / Cluster



Odometer Reading



Additional Photo 1



Additional Photo 2



ISSUES & OBSERVATIONS

Photographic evidence of the areas that need attention.



Issue 1

AC issue



Issue 2

Normal tyres



Issue 3

Engine Sound



1. EXTERIOR & TYRES

Perfect parts : **18** | Imperfect parts : **28** · Score 3.4/5

PARAMETER	CONDITION	REMARKS
Bonnet	Good	
Roof	Not Checked	
Boot Lid	Fair	
Front Left Door	Needs Attention	
Front Right Door	Fair	
Rear Left Door	Good	
Rear Right Door	Needs Attention	
Front Bumper	Fair	
Rear Bumper	Good	
Front Left Fender	Good	
Front Right Fender	Fair	
Rear Left Quarter Panel	Needs Attention	
Rear Right Quarter Panel	Fair	
Headlamp Left	Good	
Headlamp Right	Fair	
Tail Lamp Left	Needs Attention	
Tail Lamp Right	Fair	
Front Fog Lamp Left	Fair	
Front Fog Lamp Right	Fair	
ORVM Left	Fair	
ORVM Right	Good	
Front Windshield	Needs Attention	
Rear Windshield	Fair	
Window Glass Front Left	Good	
Window Glass Front Right	Fair	
Window Glass Rear Left	Needs Attention	
Window Glass Rear Right	Fair	

PARAMETER	CONDITION	REMARKS
Wiper Blades	Good	
Washer System	Good	
Overall Paint Condition	Fair	
Overspray / Repaint Evidence	Needs Attention	
Panel Gap Alignment	Fair	
Chrome & Body Trims	Needs Attention	
Tyre Front Left	Fair	
Tyre Front Right	Good	
Tyre Rear Left	Fair	
Tyre Rear Right	Needs Attention	
Spare Tyre Condition	Fair	
Alloy / Wheel Rim Front Left	Good	
Alloy / Wheel Rim Front Right	Good	
Alloy / Wheel Rim Rear Left	Good	
Alloy / Wheel Rim Rear Right	Good	
Wheel Alignment / Tracking	Good	
Underbody Rust Check	Good	
Underbody Damage / Scratches	Good	
Front Number Plate	Good	
Rear Number Plate	Fair	

Genie Assure · GBR-S5PF2EAL · Vehicle Inspection Report



2. ENGINE & TRANSMISSION

Perfect parts : 8 | Imperfect parts : 27 · Score 2.8/5

PARAMETER	CONDITION	REMARKS
Engine Start (Cold & Hot)	Fair	
Engine Idling Smoothness	Needs Attention	
Engine Noise / Knocking	Needs Attention	
Engine Vibration	Needs Attention	
Engine Oil Level	Needs Attention	
Engine Oil Condition / Colour	Fair	
Coolant Level	Good	
Coolant Condition	Fair	
Radiator Condition	Needs Attention	
Radiator Fan Operation	Needs Attention	
Thermostat	Needs Attention	
Water Pump	Fair	
Drive / Serpentine Belt	Fair	
Timing Chain / Tensioner	Good	
Air Filter	Good	
Fuel Lines / Leaks	Fair	
Oil Leaks (Engine Bay)	Fair	
Engine Bay Cleanliness	Needs Attention	
Battery Condition	Needs Attention	
Battery Terminals / Corrosion	Fair	
Spark Plugs	Fair	
Clutch Operation	Good	
Gear Engagement	Good	
Gear Shift Smoothness	Fair	
Reverse Gear	Fair	
Neutral Gear	Needs Attention	
Transmission Oil Level	Good	

PARAMETER	CONDITION	REMARKS
Drive Shaft / CV Joints	Fair	
Differential Noise	Needs Attention	
Engine Mounts	Fair	
Exhaust Note	Good	
Exhaust Smoke (White / Black / Blue)	Fair	
Catalytic Converter	Needs Attention	
Check Engine Light	Fair	
Oil Pressure Warning Light	Good	

GENIE ASSURE



3. ELECTRICALS & INTERIORS

Perfect parts : **18** | Imperfect parts : **31** · Score 3.2/5

PARAMETER	CONDITION	REMARKS
Dashboard Warning Lights	Fair	
Speedometer	Needs Attention	
Tachometer	Good	
Odometer	Fair	
Fuel Gauge	Needs Attention	
Temperature Gauge	Good	
Horn	Fair	
Headlights High Beam	Needs Attention	
Headlights Low Beam	Good	
Left Turn Indicators	Fair	
Right Turn Indicators	Needs Attention	
Hazard Lights	Fair	
Brake Lights	Good	
Reverse Light	Fair	
Fog Light Operation	Needs Attention	
Interior Cabin Lights	Fair	
Power Window Front Left	Good	
Power Window Front Right	Good	
Power Window Rear Left	Fair	
Power Window Rear Right	Needs Attention	
Central Locking	Fair	
Remote / Keyless Entry	Good	
Steering Mounted Controls	Fair	
Infotainment / Head Unit	Needs Attention	
Speakers	Fair	
USB / AUX Ports	Good	
Reverse Camera	Fair	

PARAMETER	CONDITION	REMARKS
Parking Sensors	Needs Attention	
Driver Seat Adjustment	Good	
Passenger Seat Adjustment	Fair	
Front Seat Upholstery	Needs Attention	
Rear Seat Upholstery	Good	
Dashboard Top Surface	Good	
Front Left Door Pad	Fair	
Front Right Door Pad	Needs Attention	
Rear Left Door Pad	Good	
Rear Right Door Pad	Fair	
Steering Wheel Condition	Good	
Gear Knob / Lever	Needs Attention	
Handbrake Lever	Fair	
Sunroof	Good	
Roof Lining	Fair	
Interior Odour	Needs Attention	
Carpets / Floor Mats	Good	
Cabin Cleanliness	Fair	
Driver Seat Belt	Needs Attention	
Passenger Seat Belt	Good	
Rear Seat Belts	Good	
Child Lock Operation	Good	



4. STEERING, SUSPENSION & BRAKES

Perfect parts : 12 | Imperfect parts : 21 · Score 3.1/5

PARAMETER	CONDITION	REMARKS
Steering Free Play	Fair	
Steering Return to Centre	Needs Attention	
Steering Noise	Good	
Power Steering Fluid Level	Good	
Power Steering Leaks	Fair	
Steering Column / Joints	Needs Attention	
Suspension Front Left	Good	
Suspension Front Right	Fair	
Suspension Rear Left	Needs Attention	
Suspension Rear Right	Good	
Front Shock Absorbers	Fair	
Rear Shock Absorbers	Needs Attention	
Suspension Springs	Good	
Ball Joints	Fair	
Tie Rod Ends	Needs Attention	
Suspension Bushings	Good	
Wheel Bearing Front Left	Fair	
Wheel Bearing Front Right	Needs Attention	
Wheel Bearing Rear Left	Good	
Wheel Bearing Rear Right	Fair	
Brake Pedal Feel	Needs Attention	
Brake Pedal Travel	Good	
Brake Fluid Level	Fair	
Front Brake Discs	Needs Attention	
Rear Brake Discs	Fair	
Front Brake Pads	Good	
Rear Brake Pads	Fair	

PARAMETER	CONDITION	REMARKS
Drum Brakes (If Applicable)	Needs Attention	
Brake Noise / Squeal	Good	
ABS Operation	Good	
ABS Warning Light	Good	
Handbrake / Parking Brake Effectiveness	Fair	
Brake Lines / Hoses	Needs Attention	

Genie Assure · GBR-S5PF2EAL · Vehicle Inspection Report

GENIE ASSURE



5. AIR CONDITIONING

Perfect parts : 3 | Imperfect parts : 9 · Score 3.0/5

PARAMETER	CONDITION	REMARKS
AC Compressor Operation	Fair	
AC Cooling Performance	Needs Attention	
AC Blower Speeds	Good	
AC Vents / Airflow	Fair	
AC Condenser	Needs Attention	
AC Evaporator	Fair	
AC Gas Level / Pressure	Good	
Cabin Air Filter	Fair	
AC Noise / Rattling	Needs Attention	
Heater Operation	Fair	
Rear Defogger	Good	
Climate Control Panel	Fair	

Genie Assure · GBR-S5PF2EAL · Vehicle Inspection Report



6. OTHER DETAILS

Perfect parts : 8 | Imperfect parts : 12 · Score 3.3/5

PARAMETER	CONDITION	REMARKS
Number of Keys Provided	Needs Attention	
RC Book Availability	Fair	
Insurance Validity	Good	
PUC Certificate	Good	
Service History Available	Fair	
Spare Key	Needs Attention	
Tool Kit	Fair	
Jack & Handle	Good	
Ownership Documents	Fair	
First Owner Vehicle	Needs Attention	
Total Number of Owners	Needs Attention	
Accident History Reported	Fair	
Engine Number Matches RC	Good	
Chassis Number Matches RC	Good	
Any Modifications	Good	
Odometer Reading (Kms)	Good	
Year of Manufacture	Fair	
Fuel Type	Needs Attention	
Transmission Type	Good	
Vehicle Usage Type (Personal / Commercial)	Fair	



ADDITIONAL COMMENTS

Not bad

GENIE ASSURE



GENIE ASSURE

INSPECT · VERIFY · DELIVER

Thank you for choosing us!

We truly appreciate your decision to prioritise the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your vehicle but also peace of mind for you and your loved ones.

★ **4.8**

BUYER RATING

✓ **2,500+**

INSPECTIONS COMPLETED

VEHICLE

Tata Tiago 2021

CUSTOMER

Test User

INSPECTION DATE

18 Sep, 2026

KEEP IN TOUCH

support@genieassure.com

Support: +91 89040 96262

533, 14th Cross Rd, Sahakar Nagar, Bengaluru, Karnataka 560092

